



FloodSax[®]
Flood Damage Limitation

HIGH STANNERS, MORPETH.

FLOODSAX[®]
PHOTOS TAKEN ON MON 8TH SEP 08

Combined Harvesters Ltd

Setting Sustainability Standards



Apprenticeships



www.combinedharvesters.com

Tel :0845 838 7542

High Stanners, Morpeth – FloodSax® Photos taken on Mon 8th Sep 08



High Stanners, Morpeth – FloodSax® Photos taken on Mon 8th Sep 08



See water/dirt line half way up FloodSax®

High Stanners, Morpeth – FloodSax® Photos taken on Mon 8th Sep 08



FloodSax® stopped water entering front of house –
See water / dirt line on FloodSax®



FloodSax® deployed at front porch – level of water can be clearly seen on FloodSax®

High Stanners, Morpeth – FloodSax® Photos taken on Mon 8th Sep 08



FloodSax® correctly deployed by energising first

High Stanners, Morpeth – FloodSax® Photos taken on Mon 8th Sep 08



FloodSax® deployed front and back doors

High Stanners, Morpeth – FloodSax® Photos taken on Mon 8th Sep 08



FloodSax® deployed and energised at Front Door and air vents. Level of flood water can be clearly seen on brick work.

BBC Photo- River Wansbeck at High Stanners – 10 feet higher than normal.



BBC Photo – See fridge and garden bench on top of car in Morpeth, indicating the force of the floods.

